

KEGEL PINSETTER PARTS



COMPATIBLE WITH GS® PINSETTERS
ELEVATOR



SHOVEL REBUILD KIT

163-8012


Having issues with pin loading? With many machines well over one million frames, the wear points of the shovels become extremely worn which leads to this problem. Rebuild your shovels at a fraction of the cost of a new assembly with this Shovel Rebuild Kit.



SMALL TRACK WHEEL REPLACEMENT

163-8013

REPLACES PART 47-011046-004



Worn Track Wheels can cause poor loading of the pins into the shovels. Try our Small Track Wheel Replacement to increase pin loading efficiency at an affordable price.

Contact your Kegel Distributor to order today.

WWW.KEGEL.NET
USA TOLL FREE: (800) 280 BOWL (2695)
Phone: +1 (863) 734 0200 | Fax: +1 (863) 734 0204
1951 Longleaf Blvd. Lake Wales, FL 33859 USA

